
LOMANCO Turbine Bearings

The Bare Facts

Only the finest quality American-made bearings are used in Lomanco's Whirlybird[®]. Other turbines may skimp on bearing quality, but at Lomanco[®], we know that bearings are the heart of the turbine. If they're out of round, poorly sealed or made with inferior materials, they simply won't last or run as quietly as the Lomanco[®] WhirlyBird[®].

Compare and you'll see the difference. You'll see why Lomanco® lasts forever. Guaranteed.



Compare Lomanco Bearing Quality

Design Feature	Lomanco	Competitors
Delrin® bearing rings	Yes	No
Made completely in the USA	Yes	No
100 Grade 302 series stainless balls	Yes	No
Concentric to .0015	Yes	No
Fully machined raceways	Yes	No
Turcon [®] seals	Yes	No
Self-lubricated Turcite® bearing cage	Yes	No



Scan the QR Code for special information on Whirlybird® Turbines





Once Lomanco's Whirlybird is Installed, You can Forget About it. Forever.

Simply put, you can't buy a better turbine than Lomanco's Whirlybird because it's built to last indefinitely. Once it's installed, you can forget about it, because we guarantee it forever.

When you see how we build a WhirlyBird[®], you'll see why we have the confidence to stand behind our product like we do.

American-made polymer ball bearings for silent operation and NO maintenance. Every WhirlyBird° is factory tested to turn in a breeze of less than two miles per hour.

21 Air-Foil curved vanes with rolled edges to deflect water.

Rigid spider-type construction riveted at every connection and tested to withstand 110 mph.

100% Rust-free all-aluminum construction available in mill finish, brown, black, white or weathered bronze.

Vari-pitch base fits all roof pitches up to 12/12

Also available – 14" Big Whirly[®] Moves 37% more air.

THE BEST GUARANTEE IN THE BUSINESS:

Lomanco's Whirlybird and Big Whirly are guaranteed forever. If a Lomanco turbine ventilator fails for structural or mechanical reasons, Lomanco will replace it. This warranty is transferable from the original owner to subsequent owners.

LO461_071



